



ITEM	MATERIAL	UA1R	UA1AR	ITEM	MATERIAL	UA1R	UA1AR
c	Bolt, Machine 5/8"	4	4	ek	Locknut 5/8"	5	5
d	Washer, Square 2 X 2	5	5	fm	Fiberglass Bracket Single Position	1	1
p	#6 Cu Crimpet	1	1	fm2	Fiberglass Bracket Two Position	1	1
ae	Arrester, Surge 18kV	1	1	ugc	Cable Riser Shield /Power Mold	2	2
af	Cutout, Loadbreak	1	1	ugk	Primary Terminator (Pothead)	1	1
ap	Clamp, Hot Line	1	1	uhc	MB4 Terminator Bracket	1	
ap1	Baskets, Hot Line	1	1	uhc	MB5 Terminator Bracket		1
av	Wire, #2 Insulated Tap	15'		uhc1	Kellum Grip	1	1
av	Wire, 2/0 Insulated Tap		15'	rp11	Loadbreak Cover	1	1
bo	Anchor Shackle	1	1	rp12	Arrester Bird Cover	1	1
cj	Wire, #6 Insulated Green Ground	30"	30"	rp14	Terminator Cover	1	1
dg	Eye Bolt 5/8"	1	1				

NOTES:

- Total arrester length must be under 3 ft.
- No bends permitted in cable within 6 inches of terminal base.
- Bracket item "fm" should be set to align with the cutout item "af".
- Trim the stem connector so that it does not protrude from the terminator cover.
- Terminator cover shall be installed over the first skirt of the terminator.
- Call out UA1R for 1/0 EPR Conductor.
- Call out UA1AR for 4/0 EPR Conductor.

**SINGLE-PHASE CABLE
TERMINAL POLE**

RUS

06/02/14

Rev.A



UA1R
UA1AR