



ITEM	PART #	MATERIAL	QTY
a	4311	Insulator Clamp Top	2
rp	4711	Salisbury Coverup	8'

NOTES:

1. Retrofit standard for avian protect for VC2.5 configuration with 10' crossarms.
2. Two pin insulators need to be retired and replaced with clamp style insulator.

**24.9 / 14.4 KV, 3-PHASE
DOUBLE PRIMARY SUPPORT ON CROSSARM
AVIAN SAFETY RETROFIT**

RUS
02/12/2016
REV. 0



VC2.5MA-1