



ITEM	MATERIAL	QTY
p	Connectors, compression type	6
af	Cutout, distribution open, 27 kV	3
av	Jumpers, as req'd	

NOTES:

1. Specify fuse size or solid blade.
2. Mount cutouts so that blades face climbing face of pole.

Cutouts (Three Single - Phase)

RUS

03/27/08

Rev. 0



VS1.3