



- NOTES:
1. ARRESTORS MUST BE POSITIONED FOR PROPER CLEARANCE. BRACKETS MAY BE MOVED IF NECESSARY.
 2. OPERATING MECHANISM MAY BE MOVED TO THE LEFT OR RIGHT QUADRANT OF THE POLE IF DESIRED.
 3. ARRESTORS (NOT SHOWN) SUPPLIED BY CUSTOMER.

| RATING DATA | |
|--------------------|--------------|
| CAT. NO. | 973PF-30AEFF |
| INTERRUPTING, AMPS | 600 |
| MAXIMUM KV | 25 |
| KV BILL | 150 |
| CONTINUOUS , AMPS | 900 |
| MOMENTARY, AMPS | 40,000 |

| | | | | |
|---|---------|----|----|-------------------------------|
| 2 | 8349 | 10 | SS | COTTER PIN |
| 2 | 5116-02 | 9 | GS | PIN |
| 3 | 5106-07 | 8 | | PIPE, 7" |
| 2 | 2825 | 7 | | COUPLING ASSEMBLY |
| 1 | 2493 | 6 | | HANDLE ASSEMBLY |
| 1 | 2492-03 | 5 | | LOCK SEGMENT ASSEMBLY |
| 1 | 2392-07 | 4 | | U-JOINT ASSEMBLY (FIBERGLASS) |
| 2 | 2270 | 3 | | PIPE GUIDE ASSEMBLY |

Phase Over Phase
Vector Assembly

| | | | |
|--------|----------|--|---------|
| RUS | 05/27/08 | | VS2.32V |
| Rev. 0 | | | |